

May 27, 1987

EPA

Illinois Environmental Protection Agency
Division of Land Pollution Control
2200 Churchill Road
Post Office Box 19276
Springfield, Illinois 62794-9276

Attention: Harry A. Chappel, P.E., Acting Manager
Facilities Compliance Unit

Site #1190900002 — *Madison Co*
GSX Corporation - Barton #2

Dear Mr. Chappel:

C.W. files

This letter is in response to your letter of apparent non-compliance sent to GSX Corporation (now Laidlaw Waste Systems, Inc.) dated May 19, 1987. The monitoring points noted in your letter, G104 and G105, were damaged to the point that a representative sample could not be collected for the reporting period January 15, 1987. These monitoring points were damaged while a slurry wall was being constructed around the perimeter of Barton Landfill. This slurry wall is designed to protect groundwater from potential contamination from leachate, if it were formed inside the landfill. This voluntary environmental upgrade resulted in construction activities near monitoring points G104 and G105. Various construction activities near these points caused them to be damaged so that samples could not be collected.

To remedy this situation, Laidlaw Waste Systems, Inc. installed new monitoring wells near the original locations of monitoring points #G104 and G105. The new monitoring points, designated R104 and R105, respectively, were monitored with a chemical analysis form submitted for the reporting period due April 15, 1987. These monitoring points (R104 and R105) will be monitored for all subsequent monitoring periods.

If you have any questions concerning this matter, please contact me at (314) 921-4488.

Respectfully submitted,

Chris L. Segafredo
Chris L. Segafredo
PROJECT MANAGER

cc: Mr. Charles Emde
Mr. Mike Whitlock
Mr. Charles Reeter

US EPA RECORDS CENTER REGION 5



412336

RECEIVED

JUN - 1 1987

EPA-DLPC

RECEIVED

JUN - 1 1987

EPA-DLPC

